

**COMPLETE THE FULL WOLF QC PROCEDURE BEFORE PROCEEDING WITH THIS FLOWCHART**  
Refer to "Procedure WOLF Troubleshooting rainbow bead resolution issues" for detailed instructions on how to follow this flowchart  
Estimated Time for Completion = 4 – 8 hours





